WATERIAL SAFETY DATA SHEET

LB-1683

FOR COATINGS, RESINS AND RELATED MATERIALS

		(Approved by U.S. Department of Labor "Essentially Similar"	10 FORM OSHA-501
DATE OF PREP.	s. Ima	(Approved by 0.9. Department of Eagor, Essentially Stilling)	10 1-01111 COTTA-20)
**	3.776		

Section I

MANUFACTURER S NAME

Fuller-O'Brien Corporation

STREET ADDRESS

450 East Grand Avenue

EMERGENCY TELEPHONE NO

(415) 761-2300

PRODUCT CLASS

Polyamide Epoxy Catalyst

Primer Catalyst Cl. 1 Comp. 2

CITY, STATE, AND ZIP CODE

South San Francisco, CA. 94080

75-X-24

MANUFACTURERS CODE IDENTIFICATION MBO-125-006

INGREDIENT By Volume			PERCENT	TLV		LEL	VAPOR PRESSURE
				PPM mg/M³			
	lve ic Hydrocarbon yl Alcohol		40 20 15 10	200 500 400 200		1.8 0.9 2.5 1.0	3.8 40 33 25

Section III - PHYSICAL DATA

LIGHTER, THAN AIR HEAVIER BOILING RANGE . 180-2790 F VAPOR DENSITY WEIGHT PER FASTER X SLOWER, THAN ETHER PERCENT VOLATILE
BY VOLUME OF EVAPORATION RATE

Section IV — FIRE AND EXPLOSION HAZARD DATA

FLASH POINT DOT CATEGORY Flammable - Red Label

 24° F

LEL 1.5

7.3 Pounds

EXTINGUISHING MEDIA

CO2, Foam, Dry Chemical

UNUSUAL FIRE AND EXPLOSION HAZARDS

Exposure to very high temperatures may cause volumetric expansion of the liquid and bursting of the containers.

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water stream on burning liquids.

Section	V — HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE 300 ppm		
Nausea, dizziness, skin or eye respiratory tract, narcosis.	irritation, irritation to the upper	
Inhalation: Remove to fresh a if condition pers Skin Contact: Wipe off with r	on: Contact physician immediately. ir-use oxygen if necessary-contact phy ists. ag-wash with soap and water. y of water for 15 minutes-get medical	attention
Secti	on VI — REACTIVITY DATA	1:4
STABILITY UNSTABLE STABLE INCOMPATABILITY (Materials to avoid) HAZARDOUS DECOMPOSITION PRODUCTS	conditions to Avoid Sparks and open flame.	
	Non Photochemically Reactive - Meets	Rule 66.
HAZARDOUS POLYMERIZATION MAY OCCUR CONDITIONS TO AVOID	WILL NOT OCCUR	· · · · · · · · · · · · · · · · · · ·
Section VII -	- SPILL OR LEAK PROCEDURES	2 1
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPIL	Extinguish sources of ignition. V	Jentilate
to prevent build up of vapors.	Soak up with sawdust or similar iner	ct materia
wastedisposal METHOD Discard in seale in accordance with local regul	d metal containers away from heat and ations.	flame (
	PECIAL PROTECTION INFORMATION	
RESPIRATORY PROTECTION		Allering to the second
Use respirator or mask to avoi Use air supplied respirator fo	d breathing vapor or spray mist. or work in confined areas.	
VENTILATION		មា
Local exhaust or open air.		
PROTECTIVE GLOVES If needed to preven EYE PROTECTION Safety glasses or g OTHER PROTECTIVE EQUIPMENT	et skin contact. goggles recommended.	,
Section	IX — SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store upright in sealed contain	ners away from heat and flame.	
OTHER PRECAUTIONS Keep container sealed when not Do not pour into unmarked cont Keep out of the reach of child	in use. cainers.	